m/0 3/005 FOR FILE Off

Dan Slyter 522 N. 700 E.

Washington, Utah 84780

INVOICE

Date: December 28, 1999

State Contract # 986739 Goldstrike Reclamation and Monitoring

Dec. 28, 1999 Site visit and inspection

7 hours @ \$60.00/hr -\$ 420.00 98 miles @\$.32/mile -\$ 31.36

Total Invoice

--\$ 451.36

SRAY 120.00

Hello Doug and Randy,

I changed sprinkler heads from line #3 to line #4. Heap effluent was measured at 6.2 gpm. We haven't had any rain now for 90 days. The ground was very dry. I installed about 40 more fence stays in the Land Application fence. The Smith cows had torn the fence down again, and about 100 feet of fence had to be repaired.

I repaired several other sections of fence above Echenbrecks Cabin. I ran out of time to repair the one opening below Covington and to install more stays in the bottom of the draw below the old Moose Head Pit. I'll try to find time in January to finish up the last two weak areas in the lower fence.

Dan Slyter

RECEIVEL

JAN 18 2000

DIVISION OF OIL, GAS AND MINING